INSTRUCTIONS FOR 113-955-453/ELC/R ELECTRIC WASHER CONVERSION KIT

CONTENTS OF KIT

- 1 X WASHER BOTTLE WITH CAP AND PUMP ATTACTHED
- 1 X MOUNTING BRACKET FOR THE BOTTLE
- 1 X LENGTH OF WASHER HOSE
- 1 X PUSH BUTTON SWITCH
- 1 X L SHAPED SWITCH MOUNTING BRACKET
- 1 X WIRE WITH PLUG CONNECTED
- 1 X "T" PIECE FOR HOSE
- 2 X UNIVERSAL WASHER JETS
- 2 X RUBBER WASHER FOR JETS
- 2 X METAL WASHER FOR JETS
- 2 X NUTS FOR JETS
- 2 X "P" CLIPS FOR HOSE
- 2 X SCREWS FOR "P" CLIPS
- 2 X SCREWS FOR USE WITH BOTTLE MOUNT, OR SWITCH BRACKET
 - 1. IDENTIFY THE "FUSED SIDE" OF THE FUSE BOX AND RUN A WIRE FROM THE SWITCH LOCATION DOWN TO THIS. (DON'T CONNECT YET)
 - 2. CONNECT THE ABOVE WIRE TO ONE SIDE OF THE SWICH AND TO THE OTHER POINT THE BLUE WIRE SUPPLIED IN THE KIT.
 - 3. RUN THE BLUE (AND BLACK) WIRES THROUGH TO THE LOCATION YOU ARE MOUNTING THE WASHER BOTTLE.
 - 4. WITH THE WASHER BOTTLE IN LOCATION OFFER UP THE MOUNTING BRACKET AND SECURE. (TAKE CARE WITH DRILLING, WITH REGARDS TO FUEL/BRAKE LINES.)
 - 5. EARTH THE BLACK WIRE NEXT TO THE WASHER BOTTLE ON A CLEAN PIECE OF BARE METAL
 - 6. CONNECT THE TWO PLUGS TOGETHER, ONE FROM SWITCH ONE FROM THE PUMP.

- 7. RUN THE PROVIDED HOSE, IF NEED BE TO THE WASHER JETS, OR LOCATE AND MOUNT WASHER JETS PROVIDED.
- 8. LASTLY CONNECT THE FIRST WIRE TO THE "FUSED" SIDE OF THE FUSE BOX AND TEST.